

# Concrete Shower Pan Cracking

**Dirk Duffner**  
**Duffner Engineering**  
**[dduffner@duffnerengineering.com](mailto:dduffner@duffnerengineering.com)**

# Summary

- **Cracks were discovered in concrete shower pans after only a few months of service.**
- **We conducted an analysis to determine the stress in the pan associated with non uniform drying of the concrete during manufacturing, and with distortion of the pan during installation and usage.**

# Typical Concrete Shower Pan






# Crack Discovered in the Curb





# Curb Crack Close-up



# Non Uniform Drying Analysis

- Drying Shrinkage = 200 to 800  $\mu\text{in/in}$ ; use 400  $\mu\text{in/in}$
- Density = 0.0839  $\text{lb/in}^3$
- $E = 4 \times 10^6$  psi
- $\nu = .21$
- CTE = 10  $\mu\text{in/in/deg C}$
- Simulate 400  $\mu\text{in/in}$  non uniform drying with thermal stress  $\Delta T = 40$  deg c
- All exposed surface nodes = 10 deg C
- All other nodes = 50 deg C

# Shower Pan

- **Length = 48 in**
- **Width = 42 in**
- **Thickness = 2 in**
- **Curb Height = 6 in**
- **Strength = 350 psi**



# Boundary Conditions

- **Pan restrained in vertical direction – all bottom surface nodes set to 0 displacement in y (vertical) direction**
- **Pan not allowed to curve as a result of shrinkage**




# Non Uniform Drying Shrinkage

Principal Stress 1





# Non Uniform Drying Shrinkage





# Vertical Restraint Along Curb

Principal Stress 1



# No Vertical Restraint

Principal Stress 1





# Remove Shrinkage

- **Bending stress**
- **Upward floor heave**
- **Upward vertical displacement**
  - **2 line deflections crossing at drain**
- **Curb edge restrained**

# Upward Heave of Floor .04 Inches

Principal Stress 1

